



June 30, 2021

Emailing the Denver Fire Dept. your suppression system impairment reports

Greetings to all suppression system contractors licensed through the DFD Licensing Program,

Per section 6.4.5 and 6.4.9 of the CODE OF COLORADO REGULATIONS 8 CCR 1507-11 Division of Fire Prevention and Control (see attached document), you are obligated to send The Denver Fire Department/AHJ all suppression system impairment reports (see code sections below). Moving forward we would like all of these deficiency reports emailed to us at DFDInspectionReports@denvergov.org. When the deficiency reports are sent to this email it will generate an automated reply that will say:

“Thank you for submitting your inspection report(s) to us. Please note that this is not an actively monitored email box. Any time a fire alarm or suppression system is compromised you must notify the Denver Fire Department through the System Down Reporting Website at apps.denverfireonline.com. If a system is down for longer than 10 hours, a fire-watch Permit is required.”

6.4.5 Copies of inspection reports must be submitted to the AHJ unless the contractor is notified in writing that they do not wish to receive such reports. Impairment reports in accordance with 6.4.9 must be submitted regardless of whether the AHJ has notified the contractor that they do not wish to receive inspection reports. If possible, reports should be sent to the AHJ through telephonic or other electronic means, such as facsimile or email. If the AHJ does not have electronic communication capabilities, a report shall be deemed delivered when mailed through the US Postal Service to the AHJ.

6.4.9 Any contractor, Sprinkler Fitter, or inspector who finds a Fire Suppression System with impairments must provide a copy of the reports or records associated with that finding to the local responding fire department and the appropriate AHJ for the Fire Suppression System within 24 hours. Impairment reports must be provided regardless of whether the AHJ has notified a contractor that they do not wish to receive inspection reports in accordance with 6.4.5.

Feel free to contact us at 720-913-3474 and let us know if you have any questions regarding this new protocol.